


Kilo Moana Jason OBS Recovery Cruise Log

Lost Instruments in PLUME OBS Deployments



Final Summary

Site	Institution	Failure Mode
60	SIO	Catastrophic implosion of glass floatation
59	WHOI	Anchor jamming or mud infiltration into base grating
58	SIO	Catastrophic implosion of glass floatation
57	WHOI	Anchor jamming or mud infiltration into base grating
53	WHOI	Catastrophic implosion of glass
16	SIO	Catastrophic implosion of glass floatation
54	SIO	Catastrophic implosion of glass floatation
25	SIO	Premature release

- A total of 1 stainless bail & 3 SIO sensors were recovered. (2x T240 & 1x T40)
- A total of 2 WHOI sensor balls and 2 intact instruments were recovered.